



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 4, 2010

Reviewed:

Mine Name: Martin	Permit Number: S/007/0037
Operator Name: Quality Building Stone	Inspection Date: February 3, 2010
Inspector(s): Wayne Western	Time: 2:00 – 3:00 PM
Other Participants: Chris Conrad (BLM)	Mine Status: SUS

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection done in connection with an inspection of the Italian Tan site.

Inspection Summary:

Due to snow on the ground; visibility at the site was limited. The Operator had stated to the Division that the site had been seeded in December 2009. Therefore, all the requirements for bond release had been completed. Because there is no bond on the site the Division will retire the project.

Conclusions and Recommendations:

The Division should retire the site and close the file.

Inspector's Signature

(whw):pb

cc: (OPERATOR) Velinea Miller, Quality Building Stone

Christopher_Conrad@blm.gov

O:\M007-Carbon\S0070037-Martin\inspections\Insp_02042010.doc